



## Safety Inspection at POLAR Cutting machines and Systems

Company/Agency	Surname	First Name	Phone
M. Demajo (Graphic Arts) Ltd. Demajo House 103 Archbishop Street VLT 1446 Valletta Malta	Farrugia	Manuel	+356 2552 0000

The specialists listed here are specifically trained by POLAR on a regular basis for carrying out the safety inspections on POLAR cutting machines. Such training is always performed in addition to the relevant product training course. This ensures that the required service competence is safeguarded also for previous cutting machines being used. In order to guarantee the best possible safety for your machine and to keep this standard, the competent technicians are equipped with the necessary measuring instruments. Although they cannot relieve you of your responsibility for your staff they can certainly make sure with their work that you have a clear conscience, because you have done everything possible for the safety of your personnel.